



LEAK REPORT


Leak #:	1
Date:	December 8, 2021
Map #:	N/A
Coordinates:	

Leak Type	SERVICE LINE
Leak Address	339 HENLEY HORN BROOK RD

Client:	Pace Engineering / Hornbrook CSD	Agreement:	21071
---------	----------------------------------	------------	-------


REMARKS
VISIBLE SERVICE LINE LEAK JUST UNDER CURB STOP.

Action(s) Taken: _____
 Recommendation(s): REPAIR / REPLACE



EQUIPMENT USED
S-30
VISIBLE

LEAK INFORMATION	
Leak Consultant:	BH
Leak Class:	II
Leak Rate (GPM):	2.00
Cover Type:	METER BOX
Site Marked:	NO
Mins. Pinpointing:	20



Computer Correlation Results			
Scan Time	Grade	Dist. "Red"	Dist. "Blue"

Water Loss (gallons)	
Daily:	2,880
Weekly:	20,160
Monthly:	87,600
Annual:	1,051,200